

DIRECTORATE OF INTELLIGENCE

Industrial Facilities (Non-Military)

# Basic Imagery Interpretation Report

Major Electric Power Plants Shansi Province, China

**Top Secret** 

25X1

RCS

13/0039/70

25X1

DATE APRIL 1970 COPY 117 PAGES 8



25X1

TOP SECRET RUFF

RCS - . 13/0039/70

CENTRAL INTELLIGENCE AGENCY Directorate of Intelligence Imagery Analysis Service

### **ABSTRACT**


This report, based on 1969 photography, updates the previous Basic Imagery Interpretation Briefs and Reports on the five major electric power plants in Shansi Province, northern China. The cutoff date for information in this report is February 1970.

At the Tai-yuan Heat and Thermal Power Plant 2, a fifth cooling tower has been completed since 1968. No construction or dismantling has been observed at the other four plants since the previous reports.

On the latest coverage, the three plants at Tai-yuan and one each at Chang-chih and Ta-tung were all operating.

TOP SECRET RUFF

25X1



-2-TOP SECRET RUFF 25X1

## TOP SECRET RUFF

## INTRODUCTION

This report presents information on the current status of the following five major electric power plants in Shansi Province:

- I. Chang-chih Thermal Power Plant.
- 2. Ta-tung Thermal Power Plant Ping-wang.
- 3. Tai-yuan Heat and Thermal Power Plant I.
- 4. Tai-yuan Heat and Thermal Power Plant 2.
- 5. Tai-yuan Thermal Power Plant Steel Works Plant 2.

Requirement

COMIREX NOI Support Number 420369

25X1

Approved For Releas	se 2008/10/06 : CIA-R TOP SECRET		00010017-9	25X 25X
INSTALLATION OR ACTIVITY NAME			COUNTRY	_
Chang-chih Thermal Power Pla	_+		CH	•
UTM COORDINATES GEOGRAPHIC COOR			OH .	25X
49SFL864225* 36-19-50N II.				
MAP REFERENCE 15th RTS. USATC, Series 200 (SECRET)	, Sheet M0382-23HI	_, 3rd ed, Apr 66	, Scale 1:200,000	25X
LATEST IMAGERY USED	NEGA	TION DATE (If required)		
		NA		25X
*Action has been initiated to coordinates in the Basic Encrespectively.				_
	BASIC DESCRIPT	ΓΙΟΝ		
No apparent changes have since June 1968, the date of	e been observed at the latest photog	t the Chang-chih graphy in the pre	Thermal Power Plant vious report.	
The plant was operating the two northern stacks, and	in December 1969. three of the five	. Light smoke was spray ponds wer	s emanating from e operating.	
	REFERENCE	ΞS		
				25)
Document -				•
CIA. BCS 13/0061/69, Char (TOP SI	ng-chih Thermal Po ECRET RUFF)	ower Plant, Octobe	er 1968,	25X <sup>2</sup>
				25)
	TOP SECRET	RUFF		


Approved For Release 2008/10/06 : CIA-RDP79T00909A000900010017-9

Approved For Release	2008/10/06: CIA-RDP79T0090	9A000900010017-9	25X 25X
	4.	4	
INSTALLATION OR ACTIVITY NAME		COUNTRY	
Ta-tung Thermal Power Plant F	Ping-wang	. · CH ·	
UTM COORDINATES GEOGRAPHIC COORD	DINATES		25X
49TFQ890374 40-03-53N 113	5-12-56E		
MAP REFERENCE	Chart M0200 2441 2nd ad	Mar 68 Scala 1.200 000	<b>)</b>
2nd RTS. USATC, Series 200, (SECRET)	Sheet MO288-24HL, 2nd ed,	Mai 00, Scale 1.200,000	25 <b>X</b>
LATEST IMAGERY USED	NEGATION DATE (If	required)	
ENTEST IMPRODUCTION	Washington Sing (in	, , , , , , , , , , , , , , , , , , , ,	
		NA	25X
			<u> </u>
146	BASIC DESCRIPTION		
No changes have been obs since November 1967, the date	served at Ta-tung Thermal F		<b>+</b>
masonry stacks and vapor from operating. The status of the the poor quality of the photo	e two roof stacks could not	eight spray ponds were	Э
	1.4		149
	REFERENCES	÷.	
			25X
			207
	,,,,		
	0		
Document	930		
CIA. BCS 13/0017/69, Ta-1	tung Thermal Power Plant (F	Ping-wang), August 1968	
(TOP SEC	CRET RUFF)		25 <b>X</b>
	·		
			25X1
	-5 <b>-</b>		25/1
		l l	

Approved For Release 2008/10/06 : CIA-RDP79T00909A000900010017-9



	oved For Rele	ase 2008/10/06 : ( TOP SE(	CIA-RDP79T00909A <b>CRET RUFF</b>	.00090001001	7-9	2! 2!
				(9.040		
NSTALLATION OR AC	CTIVITY NAME	*			COUNTRY	
NSTALLATION ON A	SIIVIII IIMIL			i	OOQNTINI	
a-tung Therma	I Power Plan	nt Ping-wang			СН	
TM COORDINATES	I GEOGRAPHIC C				011	
9TFQ890374		113-12-56E				
AP REFERENCE			,	······································		
nd RTS. USAT( (SEC)	C, Series 20 RET,	00, Sheet M0288-	-24HL, 2nd ed, Ma	r 68, Scale	1:200,000	2
ATEST IMAGERY US	ED		NEGATION DATE (If requ	uired)		
						2
				NA		_
	•	BASIC D	ESCRIPTION			
No change	s have been	observed at Ta-	-tung Thermal Pow	er Plant Pin	ig-wang.	
ince November	1967, the d	late of the late	est photography i	n the previo	ous report.	
A.		المحجأ بالملاحية المناف		*	onds were	
perating. The	e status of	the two roof s	ng towers. All e tacks could not b	eignt spray p be determined	d due to	
perating. The	e status of	the two roof s <sup>a</sup>	ng fowers. All e tacks could not b ERENCES	eignt spray p e determined	d due to	
perating. The	e status of	the two roof s <sup>a</sup>	tacks could not b	eignt spray p	d due to	
perating. The	e status of	the two roof s <sup>a</sup>	tacks could not b	elgnt spray poe determined	d due to	2
perating. The	e status of	the two roof s <sup>a</sup>	tacks could not b	eignt spray p	d due to	2
perating. The	e status of	the two roof s <sup>a</sup>	tacks could not b	e determined	d due to	2
perating. The	e status of	the two roof s <sup>a</sup>	tacks could not b	eignt spray p	d due to	2
perating. The	e status of	the two roof s <sup>a</sup>	tacks could not b	eignt spray p	d due to	2
perating. The poor quali	e status of	the two roof s <sup>a</sup>	tacks could not b	e determined	d due to	2
perating. The poor quali	e status of	the two roof s <sup>a</sup>	tacks could not b	eignt spray p	d due to	2
perating. The poor quali	e status of ty of the ph	the two roof sonotography.  REF	tacks could not b	e determined	d due to	
perating. The poor quali	e status of ty of the ph	the two roof sonotography.	tacks could not b	e determined	d due to	
perating. The poor quali	e status of ty of the ph	the two roof sonotography.  REF	tacks could not b	e determined	d due to	
perating. The poor quali	e status of ty of the ph	the two roof sonotography.  REF	tacks could not b	e determined	d due to	
ocument	e status of ty of the ph	the two roof sonotography.  REF	tacks could not b	e determined	d due to	
ocument	e status of ty of the ph	the two roof sonotography.  REF	tacks could not b	e determined	d due to	
ocument	e status of ty of the ph	the two roof sonotography.  REF	tacks could not b	e determined	d due to	
perating. The he poor quali	e status of ty of the ph	the two roof sonotography.  REF	tacks could not b	e determined	d due to	
perating. The poor quali	e status of ty of the ph	the two roof sonotography.  REF	tacks could not b	e determined	d due to	
ocument	e status of ty of the ph	the two roof sonotography.  REF	tacks could not b	e determined	d due to	
perating. The he poor quali	e status of ty of the ph	the two roof sonotography.  REF	tacks could not b	e determined	d due to	2
perating. The he poor quali	e status of ty of the ph	the two roof sometography.  REF  Ta-tung Thermal SECRET RUFF)	tacks could not b	e determined	d due to	25



# **Top Secret**

# **Top Secret**